WOOD DESTROYING ORGANISM

APR 02, 2020



CLIENT

Structure(s) on Property Inspected: Single Family Residence Only
Inspection and Report Requested By: Safeline Home Inspections LLC
Report sent to Reqester and to:

INSPECTED BY



COREY RICHARDSON

License: JB279986

ID Card: JF180309

1-800-991-9095

info@ameripropest.com





Florida Department of Agriculture and Consumer Services Division of Agricultural Environment Services

WOOD-DESTROYING ORGANISMS INSPECTION REPORT

Rule 5E-14.142, F.A.C. Telephone Number (850) 617-7996

	SECTION	ON 1- GENERAL INFORMATION	
Inspection Company:			
AmeriPro Pest Control		——— Business License Number: —	JB279986
Inspection Company Name		——— Dusiness License Number. —	
3131 St Johns Bluff Rd S		——— Phone Number:	1-800-991-9095
Company Address			
JACKSONVILLE, FL 32246 Company City, State and Zip Code		Date of Inspection:	04/02/2020
Inspector's Name and Identification C	COI	REY RICHARDSON Print Name	JF180309 ID Card Number
Address of Property Inspected		Filit Name	io Card Number
	Single Femily Regidence O	alu	
Structure(s) on Property Inspected	Single Family Residence Or		
Inspection and Report requested by	Safeline Home Inspection	(Name and contact information)	
Report Sent to Requester and to:	(Name and contact information if different from above)		
SECTION 2	- INSPECTION FINDING	S- CONSUMERS SHOULD READ T	HIS SECTION CAREFULLY
STATES HEREIN THE EXTENT OF SI This report does not cover areas such as equipment, stored articles, insulation, or This property was not inspected for any fi by this report. Individuals licensed to performent on health or indoor air quality i industrial hygienist or other person traine and can reinfest seasoned wood in NOTE: This is NOT a structural present. FURTHER INVESTIGA STRUCTURAL SOUNDNESS O	UCH GUARANTEE. s, but not limited to, those that ar any portion of the structure in w rungi other than wood-decaying from pest control are not required issues related to any fungi. Persed and qualified to rend such oping a structure namely, termited damage report. It should STION BY QUALIFIED EXTERING THE PROPERTY.	re enclosed or inaccessible, areas concealed be hich inspection would necessitate removing or ungi, and no opinion on health related effects or d, authorized or licensed to inspect or report for ons concerned about these issues should consinions. A wood- destroying organism (WDIs, powder post beetles, old house borers d be understood that there may be dependent of the person of	defacing any part of the structure. r indoor air quality is provided or rendered r any fungi other than wood-destroying fungi, nor to report o sult with a certified O) means an arthropod or plant life which damages
		ollowing findings were observed: ed structure(s) may have been inaccessib	ole.)
A. NO visible signs of	WDO(s) (live, evidence, o	or damage observed)	
B. USIBLE evidence of	WDO(s) was observed as	follows:	
☐ 1. LIVE WDO(s) N/A			
	(Common Name	e of Organism and Location - use additional page, if need	led)
N/A			
, ,	, ,	sects, insect parts, frass, shelter tubes,	,
	(Common Name, Descript	ion, and Location - Describe Evidence - use additional pa	age it needed)
N/A	<u></u>		
☐ 3. DAMAGE caused by W	'DO(s) was observed and r	noted as follows:	
N/A	(Common Name, Description and Lo	cation of all visible damage - Describe damage - use add	iitional page if necessary)
<u>N</u> /A		zation of all visible damage - Describe damage - use add	
	THIS IS F	AGE ONE OF A TWO PAGE REPOR	T

inaccessible. NO INFORMATION on the status of wood-destroying organisms or damage from wood-destroying organisms in these areas is provided in this report. In addition to those areas provided in consumer information on Page 1, Section 2; the following specific areas were not visible and/or accessible for inspection. The descriptions and reasons for the inaccessibility are stated below: SPECIFIC AREAS: Wood framing members covered by insulation in the attic throughout. The master bedroom, laundry room, family room, kitchen, dining room, and front bedroom attic. **✓** ATTIC REASON: Insulation blocks view of wood members. Only the garage attic and the back bedroom attic access were accessible to be inspected. Attic area inaccessible due to low headroom and high ceilings. SPECIFIC AREAS: N/A ☐ INTERIOR REASON: N/A SPECIFIC AREAS: Exterior wall siding on the East side of the garage wall. **✓** EXTERIOR REASON: Vegetation blocks view of exterior wall siding, foundation, and trim. SPECIFIC AREAS: N/A ☐ CRAWLSPACE REASON: N/A SPECIFIC AREAS: N/A OTHER REASON: N/A **SECTION 4 - NOTICE OF INSPECTION AND TREATMENT INFORMATION EVIDENCE** of previous treatment observed: Yes No If Yes, the structure exhibits evidence of previous treatment. List what was observed: Sticker of prior termite company fixed to electric panel. Refer to attached photograph. (State what visible evidence was observed to suggest possible previous treatment - use additional page if necessary) NOTE: The inspecting company can give no assurances with regard to work done by other companies. The company that performed the treatment should be contacted for information on treatment history and any warranty or service agreement which may be in place. A Notice of inspection has been affixed to the structure at: Electrical Panel Types of Termites: This Company has treated the structure(s) at the time of inspection ☐ YES ✓ NO If YES, Common name of organism treated: Terms and Conditions of Treatment: N/A Name of pesticide used: N/A Method of treatment: Whole Structure Spot Treatment N/A Specify Treatment Notice Location: N/A **SECTION 5 - COMMENTS AND FINANCIAL DISCLOSURE** Comments: Recommend Trim or remove any plants that are in contact or proximity to home to eliminate pathways of moisture intrusion or wood destroying insects. Recommend 24" clearance between the home and any shrubbery. (Use additional pages, if necessary) Neither the Company (Licensee) nor the inspector has any financial interest in the property inspected or is associated in any way in the transaction or with any party other than for inspection purposes. Signature of License or Agent: Couy CUL Date: 4/2/2020 Address of Property Inspected: Inspection Date: 04/02/2020

THIS IS PAGE TWO OF A TWO PAGE REPORT

SECTION 3 - OBSTRUCTIONS AND INACCESSIBLE AREAS: The following areas of the structure(s)inspected were obstructed or





North







East



South




Conducive condition





Conducive condition



Conducive condition



Conducive condition



Conducive condition



Sticker on panel

WDO sticker



Previous treatment sticker